



RC Systems Safety Notice for Transmitter Model No. SenSmart 6000 (ST-44)

Product: SenSmart 6000 Transmitter (ST-44)

(For firmware versions 1.13 to 1.18)

Instruction Notice:

Technician Menu should be used by RC Systems personnel or certified technician trained by RC Systems.

When using the diagnostics menu the technician must fully exit the menu and return to the data display screen. If the user does not exit manually and the transmitter is allowed to exit the menu via the menu timeout feature, it could result in the SenSmart 6000 not working as intended.